

ENGINEERED SOLUTIONS FOR INDUSTRIES WORLDWIDE

SOLON® BELLEVILLE SPRINGS | SOLON® PRESSURE SWITCHES

TECHNICAL SERVICE BULLETIN

Document No.: D73321.19

Subject: Standard 17-7PH Condition Now TH1050 Per AMS2759/3 REV J

Part Numbers Affected: All Solon catalog 17-7PH washers processed starting in June

2024

Condition: Solon historically offered a mix of 17-7PH material conditions for different applications. These include TH1050, RH950, and a proprietary method.

Cause: A universally accepted material condition for 17-7PH material was not chosen for all catalog washer designs.

Diagnosis: Solon does not provide a consistent, industry-accepted material condition for 17-7PH catalog washer designs.

Correction: Starting in 2024, Solon will provide a catalog offering of 17-7PH washers that complies with the industry standard TH1050 condition, per AMS2759/3 REV J. Solon is still capable of offering custom heat treat options upon request.

Approved By: T. Burg Approved Date: 06/04/2024

Originated By: N. Smith Original Issue Date: 06/04/2024